

Subject NPRM paragraph (g) proposed to mandate modification per Airbus Service Bulletin A320-52-1112 Revision 02. The current Service Bulletin is of Revision 05 having a new parts kit number different from that in Revision 02. We respectfully request your office to consider including reference up to and including Revision 05 as the modification instruction with one exception.

Revision 03 and Revision 04 did not change the contents of the Service Bulletin. Revision 05 of the Service Bulletin added a "dot" placard PN D5211076320000 to the modified girt bar for identification. This identifying placard appears to be self sticking with adhesive and does not change the part number of the modified girt bar. AWWA believes the placard will eventually come off and cause compliance issues in the future even though there are currently no such reports per Airbus Industries. Therefore, we respectfully request the placard not be part of the mandatory requirement.